User:

Wednesday, 05/11/2008 1:10:18 PM

Linda Lacelle

## **Process Sheet**

Customer

: CC-DAR01 Dart Aerospace Ltd.

Job Number

: 43217

**Estimate Number** P.O. Number

Prsht Rev.

First Issue

Written By

Comment

Previous Run

: 10804

This Issue

: 05/11/2008

: NC

: 05/11/2008 : 00015

Type

S.O. No. :

: SMALL /MED FAB

**Part Number** 

**Drawing Name** 

: D3562042 : DISASSEMBLE

: D412-630-034

**Drawing Number** 

**Project Number Drawing Revision** 

Material

: 12/11/2008 **Due Date** 

Qty:

1 Um:

Each

**Additional Product** 

Checked & Approved By

Job Number:



Seq. #:

**Machine Or Operation:** 

Description:

1.0

PACKAGING 1

PACKAGING RESOURCE #1







REMOVE FROM STOCK:

1 X D412-630-034 B\_4099 \$

DISASSEMBLE TO SHIP STEP WELDMENT ONLY IDENTIFY PARTS BEING RETURNED TO STOCK:



Date: User: Wednesday, 05/11/2008 1:10:18 PM **Process Sheet** Customer: CC-DAR01 Dart Aerospace Ltd. Drawing Name: D412-630-034 Job Number: 43217 Part Number: D3562042 Job Number: Seq. #: **Machine Or Operation: Description:** D412630034 2.0 Heli Access Step RH Folding Comment: Qty.: 1.0000 Each(s)/Unit Total: 1.0000 Each(s) Heli Access Step RH Folding 3.0 PACKAGING RESOURCE #1 Comment: PACKAGING RESOURCE #1 RETURN ITEMS TO STOCK, : REPACKAGE D3562-042 STEP ONLY, USING NEW B/N 43217 ADJUST ACCPAC: 4.0 QC21 FINAL INSPECTION/W/O RELEASE Comment: FINAL INSPECTION/W/O RELEASE Job Completion